# Weathertzation Assistance Program

# Work Order Bid (ID)

#### **WORK ORDER INFORMATION**

Work Order Name: 13013SH3426Work Order Type: WeatherizationAudit Name: 13013SH3426

#### **CLIENT INFORMATION**

Client ID: 13013SH3426

#### **AGENCY INFORMATION**

Client ID: 13013SH3426

Agency:Shelby County Community Services AgencyAgency Phone:(901) 222-4280Address:3772 South Hickory Ridge Mall, Suite 516Fax:(901) 222-4313

Memphis, TN 38115 Email Address:

Agency Contact: GAILLARD, GREG Work Phone:
Cell Phone:

Email Address:

Company Name & License Number:	
Contractor's Signature:	

## **COMMENT**

### **Measures**

**Measure 1** Infiltration Redctn

C		ENETRATIONS KITCH	EN SINK							
		WINDOW 1								
	CAULK	WINDOW 2 AND REPL	ACE BROK	(EN P	ANE TOP (3	8X26)				
		WINDOW 5								
		WINDOW 6								
	CAULK	WINDOW AND BLOCK	AND SEAL	_ A/C \	WINDOW U	NIT				
	COMPLI	ETE#7								
		CE BROKEN PANE BO								
		WINDOW AND REPAIR	R TOP (LIP)	OF V	VINDOW					
		WINDOWS 10 AND 11								
		ERSTRIP AND THRES								
		ERSTRIP AND THRES		E DOC	R(DEN)					
	WEATH	ERSTRIP ATTIC STAIF	₹S							
					Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty Unit Cost Total Qty Unit Cost Total						
1	Miscellaneous Su	Infiltration Reduction	Each	1						
2	Labor	Infiltration Reduction	Each	1						
0	ther Detail									
			ı	Measur	e Sub Total:		] .	Sub Total:		
	Field Notes:									

**Components** 

Inspected

Measure 2 Rep	lace A/C			Componen	ts AC3		ı	Inspected
Comment REPLAC	CE A/C WINDOW UNIT	COMPLET	E 24,0					
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Cooling Equipmer	Window A/C -	Each	1					
2 Labor	Window A/C -	Each	1					
Other Detail								
			Measur	e Sub Total:		•	Sub Total:	
Comment REPLAC	lace Htg. System CE WALL HEATER COM WALL HEATER 15 FT)	IPLETE S	INGLE	Componen 35,000 BTU  Estimated			Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Heating Equipmer	-	Each	1					
2 Labor	REPLACE WALL HEATER COMPLETE SINGLE 35,000 BTU	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

Measure 4 Floo	or Ins. R-19			Componen	ts FD1		ı	nspected
Comment 2301 Se	Q FT.							
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	<b>Unit Cost</b>	Total
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	2301					
2 Labor	Floor Insulation - Fiberglass Batts - R-19	SqFt	2301					
Other Detail						_		
			Measur	e Sub Total:		] ,	Sub Total:	
	Monitor is Needed L 2 CO.MONITORS			Componen	ts		ı	inspected
				Componen Estimated			I Actual	nspected
Comment INSTAL		Units	Qty	-		Qty		nspected Total
Comment INSTAL	L 2 CO.MONITORS  Description / Comment	<b>Units</b> Each		Estimated		Qty	Actual	
Comment INSTAL  # Material / Labor	L 2 CO.MONITORS  Description / Comment		Qty	Estimated		Qty	Actual	
<ul><li>Comment INSTAL</li><li># Material / Labor</li><li>1 Health and Safety</li></ul>	L 2 CO.MONITORS  Description / Comment CO monitor	Each	Qty 2	Estimated		Qty	Actual	
<ul><li>Comment INSTAL</li><li># Material / Labor</li><li>1 Health and Safety</li><li>2 Labor</li></ul>	L 2 CO.MONITORS  Description / Comment CO monitor	Each	Qty 2	Estimated		Qty	Actual	
<ul><li>Comment INSTAL</li><li># Material / Labor</li><li>1 Health and Safety</li><li>2 Labor</li></ul>	L 2 CO.MONITORS  Description / Comment CO monitor	Each	Qty 2	Estimated		Qty	Actual	
<ul><li>Comment INSTAL</li><li># Material / Labor</li><li>1 Health and Safety</li><li>2 Labor</li></ul>	L 2 CO.MONITORS  Description / Comment CO monitor	Each	<b>Qty</b> 2 2	Estimated			Actual	
<ul><li>Comment INSTAL</li><li># Material / Labor</li><li>1 Health and Safety</li><li>2 Labor</li></ul>	L 2 CO.MONITORS  Description / Comment CO monitor	Each	<b>Qty</b> 2 2	Estimated Unit Cost			Actual Unit Cost	

	Measure 6 Pres	sureRelief Piping Need	ded	(	Compone	nts			Inspected
C	Comment								
					Estimate	d		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Pressure relief piping	Each	1					
2	Labor	Pressure relief piping	Each	1					
C	Other Detail			1					
				Measure	Sub Total:		,	Sub Total:	
	-	or Barrier Needed ement/CrawIspace) FT.		(	Compone				Inspected
	Matarial (Labor	December 10 mm mm	11-11-		Estimate	<del></del> -		Actual	T- (-1
	Material / Labor Health and Safety	Description / Comment  Basement / crawlspace vapor barrier	<i>Units</i> SqFt	<b>Qty</b> 2301	Unit Cost	Total	Qty	Unit Cost	Total
2	Labor	Basement / crawlspace vapor barrier	SqFt	2301					
C	Other Detail								
				Measure	Sub Total:			Sub Total:	
	Field Notes:								
			Work O	rder Gran	d Total:		Gran	d Total:	

Client ID: 13013SH3426